**4-Point Inspection Report** 

# Paul J. Customer

### 1234 Anywhere Drive

### Your Town, FL



7/31/2012

Thomas M. Tillman

CGC1516754 - HI5543 ttillman@brinedevelopment.com

### Brine Development Services, LLC

CGC1516754 Apollo Beach, Florida 33572 (813) 699-4200

www.brinedevelopment.com

# **Four- Point Inspection Report**

Note: A Four-Point Insurance Inspection is typically performed for a homeowner when requested by their insurance company to obtain a new insurance policy or renewing an existing policy.

A Four-Point Insurance Inspection is far less in scope than a standard home inspection. This Four-Point Insurance Inspection is a limited, visual survey of the heating/air conditioning, roof, electrical and plumbing systems.

Date of inspection:	7/31/2012	
Property's Address:	1234 Anywhere Drive	
Property's City, State, Zip Code:	Your Town, FL	
Type of home:	Single Family	
Type of construction:	CMU Block	
Type of foundation:	Concrete	
Number of stories:	1	
Approximate square feet:	2746	
Approximate total living area:	2315	
Approximate age of home:	24 years (Built) 1988	
Client/owner's name:	Paul J. Customer	
Insurance company/policy number:		
Inspector's name:	Mark Wise	Tom Tillman
License number	CGC1520217-HI6150	CGC1516754-HI5543
Inspector's signature:	Inspector's Signature	
Inspector's company name:	Brine Development Services, LLC	
Inspector's address:	6625 Dolphin Cove Drive	
Inspector's city, state, zip code:	Apollo Beach, FL 33572	
Inspector's email address:	captmark13@msn.com	tomtill@aol.com
Inspector's phone number:	813-376-2222	813-230-2111

### **General Information:**

## Heating/Air Conditioning:

Types of heating systems:	Central/Electric
Estimated age of heating systems:	11 Years
Heating systems upgraded? Year?	8/1/2001
Condition of heating systems:	Good
Fuel Tank located?	N/A
Heating system comments:	Good
Types of cooling systems:	Central/Electric
Estimated age of cooling systems:	11 Years
Cooling systems upgraded? Year?	8/1/2001
Condition of cooling system:	Good
Cooling system comments:	Appears to be in good condition

# **Plumbing:**

Number of bathrooms:	2 & 1/2	
Overall water pressure:	Good	
Main supply line material:	PVC	
Main waste/vent material:	PVC	
Fixture supply line material:	CPVC	
Fixture drain line material:	PVC	
Shut off valves present:	Yes	
Water heater location?	Garage	
Water heater fuel type?	Electric	
Approximate age of water heater:	10 Years	
TPR valve present?	Yes	
Fire sprinkler system present?	N/A	
Freeze hazards noticed?	N/A	
Polybutylene noticed?	None	
Plumbing leaks noticed?	None	
Recent plumbing upgrades? Year?	Per Customer 1998-1999	
Overall plumbing condition:	Good	
Plumbing comments:	Photos show plumbing upgraded to PVC and CPVC	

## Roof:


Roof style:	Gable
Type of roof covering:	Asphalt-Fiberglass Dimensional Shingles
Estimated age of roof covering	Installed 5/31/2002
Number of shingle layers:	1
Type of sheathing:	Plywood
Flashing damage noticed?	None
Missing shingles or covering?	None
Truss or rafter damage noticed?	None
Evidence of active leaks?	None
Estimated life expectancy:	10-12 Years
Roof comments:	Good Condition

## **Electrical:**

Service amps:	200
Size of service sufficient?	Yes
Fuses or Circuit breakers?	Circuit Breakers
Main panel location:	Garage
Panel ground observed?	Yes
GFCIs present where required?	Yes
AFCIs present in bedrooms?	N/A
Aluminum branch circuits?	None
Active knob and tube wiring?	None
Exposed or unsafe wiring noticed?	None
Recent upgrades? Year?	No
Overall electrical system condition:	Good
Electrical comments:	

# **Other Comments**

Are there any deficiencies which need correction? If so, explain.	N/A
When will the deficiencies be corrected? Please provide an approximate date of completion.	N/A
Have all deficiencies been corrected? If so, when was this work completed?	N/A







Kitchen Sink Plumbing PVC Drain Lines & CPVC Supply Lines



Bathroom Plumbing PVC Drain Lines & CPVC Supply Lines







Main Breaker Panel Aluminum Stranded Main Service

Main Breaker Panel Copper Branch Wiring